











## PHOTO REPORT




Job No. : 2270

Date : 17th December 2014  
Location : Tanjung Pelepas Port

Pg1

No.	Description	
	<b>Subject : <u>Overboard Valve Replacement</u></b>	
	 <p>Leaked valve wrapped in cement box</p>	 <p>After removal of cement box</p>
	 <p>Dismantling connecting steam pipe</p>	 <p>Dismantled steam blow pipe</p>

No.	Description	
	 <p data-bbox="331 835 448 861">New Valve</p>	 <p data-bbox="760 835 860 861">Old Valve</p>
	 <p data-bbox="1138 835 1287 861">After removal</p>	
		 <p data-bbox="1062 1520 1312 1650">Carried out machining on flange hole in order to fit on existing pipe flange connection.</p>

No.	Description	
	 <p data-bbox="324 934 760 976">Fabricated gasket with ship's material</p>	 <p data-bbox="836 934 1271 976">Installed new valve in place</p>
	 <p data-bbox="246 1728 792 1770">Re-installed steam pipe in place</p>	 <p data-bbox="812 1728 1344 1770">Diver unplugged and no leakage were found</p>