

# PHOTO REPORT

Job No : 2294

Date : 31/1/2015

Location : Singapore IPL

Pg1

No.	Description
<b>Job Scope : Sea Water Pipe Repair</b>	
Work shop fabrication	
	
Welding	Grinding
	
Cutting rubber sheet	After fabrication
	

Onboard vessel



Identified the crack



Applying glue to stop leaking



Clamped up and tightened



No leak was found



Inspected by chief engineer



**Job Was Done All Progress Was Inspected By Chief Engineer Satisfactorily.**