

# PHOTO REPORT

Messr.

Job No. : 2365

Vessel

Date : 7th of May

Location : PSA Singapore

Pg1

No.	Description
-----	-------------

**Subject Workscope : Transformer Room Ducting Modification**




Measured and crop off the existing ducting in order to do the modification.



Elbows and End Caps modification, Filter renewal, and Insulation were carried out in situ.



All Elbows Joints and End Caps were fitted accordingly and Silicone paste were applied in all the joint corners.





**Above All Job Was Done. All Work Progress Was Inspected, Witnessed, And Accepted By Chief Engineer With satisfactorily.**

No.	Description
<p><b>Subject / Workscope : No:1 Air Conditioner Unit Water Eliminator Renewal.</b></p>	
<p>Removed Existing damaged Water Eliminator From the AHU unit no1</p>	
<p>Removed existing insulation and silicone. And new insulation were fabricated in situ and fixed up.</p>	



The New Air Conditioner Unit Water Eliminator were installed in place.



**Above All Job Was Done. All Equipments Were Installed Back in Good Order.  
All Job Progress Was Inspected, Witnessed And Accepted  
By Chief Engineer With Satisfactorily.**