







PHOTO REPORT

Job No. : 2372

Date : 15 And 16th May 2015

Location : PSA Singapore

No.	Description	Pg1
Subject/Workscope : High Sea Chest Rubber Coating (port side)		
		
		
<p>Opened up the High sea chest (Port Side) and extract the filter. Isolated the damages in the sea chest and marked all spots.</p>		



Cropped off all the damaged rubber coating in the sea chest.



After cropped off the damages Chief Engineer were witnessed the progress and found Satisfactory.



Well grinded all the spots and made smooth surface.



Applied one layer primer coating and mixed rubber elements in situ



Applied New Rubber coating on all the spots



Above All Job Was Done. All Work Progress Was Inspected, Witnessed, Accepted By Chief Engineer With Satisfactorily