

# PHOTO REPORT

Job No. : 2381

Date : 24 And 25th May  
Location : PSA Singapore

No.	Description	Pg1
<p><b>Subject / Work Scope : M/E Wartsila RTA 96 C fuel injection pump unit no 1 and 2 Exchange.</b></p>		
		<p>Third engineer isolated and shut the fuel oil and air pipes in order to open the connections.</p>
		
	<p>Upon confirmation removed air, fuel oil, return fuel pipe, actuator pipe connections and extract the existing fuel injection pump.</p>	



Thick hard carbon layer were found around on the fuel injection pump.



Fuel pipes, fuel injection pump block, plunger, pipe caps were cleaned with diesel oil.



Cleaned and replaced ship's spare fuel injection pump in place. Applied silicone around the pump seating and tighten the foundation nuts.





Cleaned the fuel oil pipes with diesel oil and installed and new gasket were changed



All connections were installed back in order



Upon Completion Fuel Injection Pump Timing Were Carried Out And Found Satisfactory. All Work Progress Was Inspected Witnessed Accepted By Chief Engineer With Satisfactorily.