

PHOTO REPORT

Date : 14th Sept 2015
Location : Thailand Anchorage


Pg1

No.	Description	
-----	-------------	--






Subject : Reconstruction of Damaged Poop Deck (Stbd side)(Fr.29 to Fr.33)













Inspected damaged location with Surveyor & discussed through repair procedure



Thickness of steel material for deck structure to be increased




No.	Description	
	 <p data-bbox="651 891 1120 929">Bunker Station Room below poop deck</p>	
		 <p data-bbox="1018 1370 1284 1406">RENEWAL SECTION</p>
	 <p data-bbox="561 1982 933 2018">TO BE CROPPED & REMOVED</p>	 <p data-bbox="1220 1467 1412 1668">SIDE SHELL PLATE FOUND IN GOOD CONDITION. NOT DENTED ONLY SLIGHT DEFORMED.</p>







No.	Description	
		
<p>Constructed staging in affected location</p>	<p>Constructed staging in affected location</p>	<p>Bunker manifolds covered with fire blanket & soaked with fresh water.</p>
		
		

No.	Description
	
	
	

No.	Description	
		
		
		

No.	Description
	

No.	Description	
		
		
	<p>All welding on poop deck structure completed</p>	
		
	<p>Carried out vacuum test on weldment of poop deck plate, witnessed by Surveyor</p>	

No.	Description	
	 	
	 	
	<p>Carried out NDT Dye Penetrant Test on all weldment, witnessed by Surveyor</p>	
		
	<p>All works were inspected and accepted by Surveyor & C/O with satisfactory</p>	