

PHOTO REPORT

Job No. : 2604

Date : 3rd April 2016

Location : Singapore

Description	
Subject : Renewal of Hatch Cover's Container ISO Socket x 1 pc Location: Forward Main Deck (Bay01 Row01)	
	
Damaged ISO Socket on site	New ISO Socket provided by vessel for replacement
	
Damaged ISO Socket removed by gouging	New ISO Socket being welded after alignment checks
	
NDT Dye Penetrant Test being carried out	Inspection completed with satisfactory by Ship Officer