


PHOTO REPORT

Messr.



Job No. : 2632

Date : 25th May 2016

Location : OPL

No.	Description	Pg1
<p><u>Subject (A) : Starboard Damaged Fender Repair @ OPL</u></p> <p>Scope : Removal of damaged fender & to Blank off cropped ends. (Temporary repair as requested by owner)</p> <div style="text-align: center;">  </div> <p style="text-align: center;"><u>Partial starboard fender damaged.</u></p>		

No.	Description	Pg2
-----	-------------	-----



Brief outline of Operation

- 1) Hanging staging installation.
- 2) Cropping out damaged fender.
- 3) Hull surface grinded smooth.
- 4) Blanking of remaining fender.
- 5) Inspection by Owner.

PHOTO REPORT

Messr.

Job No. : 2632

Date : 25th May 2016

Location : OPL

No.	Description	Pg1
<u>Subject (B) : Temporary Hull structural Repair In Steering Gear Room.(Transom Plate) @ OPL</u>		
		
1) 02 nos Damaged Vertical Stiffeners cropped out & replaced.		