

PHOTO REPORT

Job No.: **2638**

Date: **25th May, 2016**

Location: **Waigaoqiao Terminal,
Shanghai, China**

Subject: Renewal of damaged cell guide iwo Bay 38 Row 11

The following is the damaged cell guide



1. Erect tower staging iwo the damaged cell guide area for cargo hold

FWD



2. Cut off damaged cell guide and fit back new cell guide, welded and ground





3. After job completed and container loading test had been carried out, the container was smoothly moving up and down.

Total repair: 36meter

Material: cut off angle bar 150*150*15mm to 140*140*15mm