

# PHOTO REPORT

MP-OPN-06, Rev No:A

Job No. : 2895

Date : 13th May 2017

Location : Singapore


No.	Description	Pg1
-----	-------------	-----





**Subject : Fabrication and Installation of Ropeguard in Underwater at IPL**







↑ Pre-fabricated Rope Guard in HSD Workshop

↓ New Rope Guard loaded on boat



No.	Description	Pg2
		<p>↑ New Rope Guard released into water</p>
		<p>↖ Removal of temporary support From new Rope Guard</p>
<p>Upon releasing of Rope Guard into water, Diver team assisted to position Rope Guard for installation underwater.</p>		

No.	Description	Pg3
		
↑	Diver team began operation underwater	↑ Entanglement observed around propeller
		
↑	Entanglement observed	↑ Entanglement removed and brought to surface

No.	Description	Pg4
	  <p data-bbox="734 952 1117 985">↖ ↗ Rope Guard fully welded</p>	
	  <p data-bbox="734 1153 1212 1187">↙ ↘ Rope Guard cutter position fixed</p>	

No.	Description	Pg5
-----	-------------	-----



Position of new Rope Guard well secured and carried out full welding



Upon completion of full welding securing Rope Guard, Operation photos and videos were submitted to Chief Officer/Master and acknowledged work to be satisfactory.