


Work Report

LOCATION: Yantian Terminal, Shenzhen, China

The following location cell guide dent:



2. Cropped off damaged cell guide



3. Carried out welding



4. Completed welding



5. After touch up painting and in final condition





After job completed, removal of scraps from Vessel.

Chief Officer carried out final inspection and satisfied with our job.