



PHOTO REPORT

Messr.

Date : 28th Sept 2017
Location : Singapore IPL
Job No. : 3001

No.	Description	Pg1
Subject : Renewal of Portside Anchor Chain (1st length)		
<div style="display: flex; justify-content: space-around;">   </div> <p style="text-align: center;">Obtained hot work permit, vessel landed anchor onto barge & commenced hot work</p> <div style="display: flex; justify-content: space-around;">   </div>		

No.	Description	Pg2
		
<p>Gas cut & removed 1st & 2nd kenter shackles and replaced with new spares.</p>		
		
		

No.	Description	Pg3
		
<p>Tapered pin inserted, taper pin hole pre-heated, filled with lead, hammered & sealed 1st kenter shackle</p>		
		
		

No.	Description	Pg4
		
		
		<p>First length anchor chain replacement completed.</p> <p>While vessel hoist up anchor and chain, found no defects & nicely positioned back in anchor pocket.</p>