



PHOTO REPORT





Job No: 3482
Date: 22th December 2018.
Location: Hai Phong Port Alongside.

No.	DESCRIPTION	Page 1
1	STBD ACCOMMOUDATION LADDER:	
1.1	MOVE OUT HANDRAIL, STANCHIONS KEPT ACC. LADDER AT SAILING POSITION:	
		
		

No.	DESCRIPTION	Page 2
1.2	DYE PENETRAION TESTING THE CRACK OF LADDER STEP AND FRAME:	
		
		

No.	DESCRIPTION	Page 3
1.3	GOUGING OUT ALL CRACK WELDING SEAMS BY GRINDER:	
1.4	STRAIGHTENED BY HYDRAULIC JACK, CHAIN BLOCK AND HAMMER:	

No.	DESCRIPTION	Page 4
		
		

No.	DESCRIPTION		Page 5
			
1.5	RE-WELDING		
			

No.	DESCRIPTION	Page 6
1.5	DYE CHECK AFTER WELDING:	
		

No.	DESCRIPTION		Page 7
1.6	OPERATION AND LOAD TEST:		
	