

PHOTO REPORT

Job No. : 2410
Date : 23 Jul '15
Location : TPP, Malaysia

Description

Subject : Ventilation door renewal works IWO Bay 23 (3 pcs)



Cropped off all renewal door using flame cutter



Ventilation door after completely crop off



Grinding after cropping off



Condition of bottom part which required replacement



New plates were fabricated for bottom part



Replacement of 1st door bottom part



Replacement of 2nd door bottom part



Replacement of 3rd door bottom part



Hoist up new door using chain block for fitting



Fit up and commenced with full welding



Full welding completed



Grinding at the weldment



All 3 doors that has been cropped to be scrapped



DPI Test carried out on all 3 locations
and witnessed satisfactory by C/O