

PHOTO REPORT

Job No. : 2296

Date : 24 Feb '15

Location : ST Marine Tuas Yard

Pg1

No.	Description
<p>Subject / Work scope : Insulation And Covers For Aux Engine, Turbo Charger And Exhaust Pipes.</p>	
	
<p>Previous insulation were removed in turbo chargers and exhaust bellows.</p>	
	
<p>New rock wool fire blankets and reducer covers were installed</p>	



Covers for generator exhaust bellows were measured and fabricated in situ



Fabricated generator exhaust bellow covers were installed and tightened with screws

Above All Job Was Done. All Job Progress Was Inspected, And Accepted By Chief Engineer Satisfactorily.