

# PHOTO REPORT

Job No. : 2345

Date : 13th April 2015

Location : PSA singapore

Pg1

No.	Description
-----	-------------

**Subject / Workscope : Load Test On Gears Trolleys**



Prepared tools and equipments to do the load test. Every test was performed by using strong points Which were provided by Chief Engineer.



Distinguishing Number or Mark	Number Tested	Descriptions	Safe Working Load	Proof Load Applied
2098/01	1	Gear Trolley Model : Blackbear DLH Manufacturer : Dae Kyung Co.	2 Tons	2.5 Tons



Distinguishing Number or Mark	Number Tested	Descriptions	Safe Working Load	Proof Load Applied
2098/19 to 2098/25	7	Gear Trolley Model : Blackbear DLH Manufacturer : Dae Kyung Co.	3 Tons	3.75 Tons



Distinguishing Number or Mark	Number Tested	Descriptions	Safe Working Load	Proof Load Applied
2098/01 to 2098/06	6	Gear Trolley Model : Blackbear DLH 50 Manufacturer : Dae Kyung Co.	4 Tons	5 Tons



Distinguishing Number or Mark	Number Tested	Descriptions	Safe Working Load	Proof Load Applied
2098/17 And 2098/18	2	Gear Trolley Model : Blackbear Manufacturer : Dae Kyung Co.	5 Tons	6.25 Tons



Distinguishing Number or Mark	Number Tested	Descriptions	Safe Working Load	Proof Load Applied
2098/01	1	Gear Trolley Model : Blackbear DLH Manufacturer : Dae Kyung Co.	6.5 Tons	8.2 Tons

All above items were successfully proof loaded and were held for approximately ten minutes.  
All job progress was inspected, witnessed and accepted by Chief Engineer satisfactorily.