

PHOTO REPORT

Job No. : 2457
Date : 14/09/2015
Location : Singapore

Description

Subject : STBD SIDE NEW ANCHOR REPLACEMENT WORKS

Working Duration: 08Hrs



New Anchor Arrive From Trailer & Unload The Anchor To Jetty



New Anchor Load On To The Barge

Description



Lower Down Stbd Side Anchor Chain By Using Ship Winch




Cutting Of Existing Kentre Shackle And Connecting Of New Kentre Shackle



Connecting Of Kentre Shackle from Anchor Chain To Anchor Swivel



To Cover Up Pin Hole Of Kentre Shackle With Lead



Heave Up The Anchor By Using Ship Winch



Carried Out Operational Testing