

PHOTO REPORT

Job No. : 2650
Date : 4 June '16
Location : Taicang, China

Subject: Replaced the REF provision compressor, motor and Purifier.

Our Service Team was on board she calls to Tai Cang to carry out REF provision.

Supplied material:

Copper tube and connector

Works description:

Installed the compressor, motor and purifier.

Vacuumed the system

Charged Freon to system


Adjusted and tested system



Installation of the compressor



motor



oily separator



Carried out alignment test





Vaccuumed the whole system



Carried out leakage test



Charging of Freon



C/E witnessed and tested with satisfaction

