

Work Report

LOCATION: Waigaoqiao Terminal, Shanghai, China

1. Supplied new bottom bowl. The size is dia630mm x 150mm x 15mm thickness.



2. Dismantled the calorifier and brought it to ship's workshop.




3. Cropped off damaged bottom



4. Fit back new bottom and carried out welding and grinding.



5. Install the calorifier in situ.



6. Carried out pressure test and no leaking was found.



7. Covered back insulation and cover sheet.



8. Completed job and executed housekeeping.

