

# PHOTO REPORT

Messr.

Job No. : 3343

**Owner/Master Of**

Vessel

Date : 28th Sept 2018

Pg1

| No. | Description |
|-----|-------------|
|-----|-------------|


**Subject : ME FO Heater Bundle Cleaning**



Remove bundle from the packing (1.8 x 470)



Heating bundle going through the first stage chemical ultrasonic cleaning

| No. | Description  |
|-----|--|
|     |   <p data-bbox="199 896 1369 929">Bundle removed from tank for high pressure wash and going through second stage ultrasonic cleaning</p> |
|     |    |
|     |   <p data-bbox="363 1863 1209 1897">Bundle remove for high pressure wash and blow dry and ready for deliver</p>                      |