






## PHOTO REPORT

Messr.  
**OWNER / MASTER OF**

Date : 2 Dec '18  
Job No : 3442  
Location : Haiphong, Vietnam

No.	Description
<b>Subject: Shiplside Fenders Repair</b>	  <p style="text-align: center;"><b>Preparation of Staging materials prior to start of job</b></p>   <p style="text-align: center;"><b>Ginding and gouging prior to rewelding cracked fenders</b></p>





Rewelding and grinding upon completion

Total Done : Port 19 Locations

Starboard 27 Locations



Le Quang Trung  
HSD Marine & Shiprepair Pte Ltd