

PHOTO REPORT

Messr.

Date :30 December, 2018

Location : Singapore

Job No. : 3488

No.	Description	Pg1
-----	-------------	-----

Subject : Dump Condenser Exchange

Existing condenser with name plate



New condenser with name plate



No.	Description	Pg2
-----	-------------	-----



Existing condenser removed end cover and pipe connections



No.	Description	Pg3
-----	-------------	-----

Removed existing condenser from foundation to shift out from engine room



No.	Description	Pg4
New condenser shift into on locations		
		
		

No.	Description	Pg5
		
<p>Install back end cover and all the pipe line with new gasket (owner supplied)</p>		
		

No.	Description	Pg6
		
		

No.	Description	Pg7
-----	-------------	-----

Refit all the pipe line and foundation tighten with new condenser

