

PHOTO REPORT

Messr.

Job No. : 3511



Date : 25th Jan 2019



Pg1

| No. | Description |
|---|--|
| Subject : Stbd Provision Crane Repair Works | |
|  |  |
|  |  |
| <p>HSD Team Inspected On-board Existing stbd provision crane condition at China</p> | |

| No. | Description |
|--|---|
|  |  |
|  <p data-bbox="459 1899 1126 1926">Discuss onboard and erect staging in singapore anchorage</p> | |

| No. | Description |
|---|--|
|  |  |
|  |  |
| <p>Fabricate and install the H-beam for secure crane boom in position then crop and remove damaged crane frame.</p> | |

| No. | Description |
|--|--|
|  |   |
| <p>To remove the crane foundation to bring engine room for fairing and straightenup to repair.</p> | |
|  |  |
|  |  |

| No. | Description |
|---|--|
|  |  |
| <p>To crop and remove the roller box from damaged frame and install back with new crane frame To fabricate and install the new frame on place</p> | |
|  |  |

| No. | Description |
|---|--|
|  |  |
| <p>Upon completion of works to check crane function test with superintendent and captain</p> | |
|  |  |