

PHOTO REPORT

Job No. : 2253-2

Pg1

| No. | Description | |
|-----|-------------|--|
|-----|-------------|--|


Subject : Renewal of bitter end plating in Starboard Side chain locker



Tug & 120ft Work Barge Alongside



Anchor & Anchor Chain ranged out on barge deck



Secured anchor chain with lashing rope


| No. | Description | |
|-----|-------------|--|
|-----|-------------|--|



New Material pre-cut in workshop. Marked and pre-fabricate on-site based on existing masurement.



Base Plate Fitted



Bitter End Fitted



Support Bracket Fitted



Carried out gouging to build new bevel for full welding.

| No. | Description | |
|-----|---|---|
| |  | <p>From Internal side Of Base Plate & Bitter End Fully Welded</p> |
| |  <p>Fully welding completed</p>  | |
| |  <p>Work inspected by Surveyor & Master</p>  <p>Ship Crew painted on renewed area</p> | |