

PHOTO REPORT

Messr.

Job No. : 2533
Date : 24/12/2015
Yr PO No. : 4504225381

No.	Description	Pg1	
	<p><u>Subject / Workscope Repair of Lashing Gearbox Bin @ PSA Terminal</u></p> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  </div> <div style="width: 50%; text-align: center;">  </div> <div style="width: 50%; text-align: center;">  </div> <div style="width: 50%; text-align: center;">  </div> </div>		

No.	Description	Pg2
		

No.	Description	Pg3
		

No.	Description	Pg4
		

No.	Description	Pg5
		

No.	Description	Pg6
		