











PHOTO REPORT


- **Job No : 3588**
- **Date: 14th April 2019.**
- **Start work onboard: 0800LT 14 April.**
- **Completed: 16300LT 14 April.**
- **Location: VIP GREEN PORT (VNHPVGP).**

No.	DESCRIPTION	Page 1
1	RENEWAL CELL GUIDES IN CARGO HOLD No.3, BAY 14 ROW9 FWD – STBD; BAY 14 ROW 9 AFT – PS & STBD	
1.1	BEFORE CUTTING:	
		
		

No.	DESCRIPTION	Page 2
1.2	CUTTING DAMAGE CELL GUIDES:	
		
		

No.	DESCRIPTION	Page 3
1.3	FITTING NEW CELL GUIDES:	
		
		

No.	DESCRIPTION	Page 4
1.4	WELDING AFTER FITTING:	
		
		

No.	DESCRIPTION	Page 5
1.5	AFTER WELDING AND FINAL INSPECTION:	
		



No.	DESCRIPTION	Page 7
1.6	DYE CHECK:	

